



HS1 dni-TO-220 HS TALL
 X21 dni-4-40x3/8 SCREW
 X24 dni-4-40 NUT
 Heatsink for U1
 Use thermal compound when mounting

HS2 TO-220 HS TALL
 X22 4-40x3/8 SCREW
 X25 4-40 NUT
 Heatsink for U2
 Use thermal compound when mounting

HS3 TO-220 HS TALL
 X23 4-40x3/8 SCREW
 X26 4-40 NUT
 Heatsink for U3
 Use thermal compound when mounting

ST1 2X2 Staple
 X1 X11 SKT SKT
 X2 SKT SKT
 Fastener for J2-J5

X27 Jumper
 Jumper for JP1

Sockets for J1

X1 SKT	X11 SKT
X2 SKT	X12 SKT
X3 SKT	X13 SKT
X4 SKT	X14 SKT
X5 SKT	X15 SKT
X6 SKT	X16 SKT
X7 SKT	X17 SKT
X8 SKT	X18 SKT
X9 SKT	X19 SKT
X10 SKT	X20 SKT

Copyright 2008, Scott Cowling, WA2DFI
 Released under TAPR Non-commercial Hardware License.
<http://www.tapr.org/NCL>

Title LPU Schematic		
Size B	Document Number	Rev B
Date: Tuesday, January 27, 2009	Sheet 1 of 1	